## APPENDIX A - GENERAL FUND GROWTH BIDS Stevenge monotion council not agreed Scoring: not agreed

							Stevenage BOROUGH COUNCIL		not agreed 0 agreed 1		
Scheme	Priority	2022/2023 Growth Bid	2023/2024 Growth Bid	2024/2025 Growth Bid	2025/2026 Growth Bid	Reason for Request	Any other Relevant Information	Service	Average Score for 22/23 Growth Bid	ОИТСОМЕ	
Priority 3: Mandatory requirements (including Heal	th & Safety)										
EPC remedial	3	200,000				To comply with current regulations. Energy improvements to achieve an energy rating of E or better required to existing let commercial properties.	Cost estimates based on improvement works required to anticipated 15 properties at average cost £15K = £250K	F&E	1.00	APPROVED	
Daneshill fire doors	3	150,000				Estimated growth bid required to upgrade the fire doors as detailed in the Fire Risk Assessment.	Estimated bid based on original tender returns. Scope of works are being reviewed by the fire company to reassess the risk while taking into account the remaining life of the building.	F&E	Decision deferred pending the challenge on whether the doors really do need replacing	DEFERRED	
Fire stopping works at SALC	3	100,000				Recent fire risk assessment has identified the requirement to undertake these works, we need to undertake further investigations to ascertain exact cost of priority works	The cost is currently estimated for investigations are being undertaken	C&N	1.00	APPROVED	
MSCP lighting upgrade - LED (phased)	3	75,000	75,000	75,000		To ensure adequate lighting levels are maintained. High level replacements / maintenance. Legislation in Sept 2023 phasing out the sale of Flourescent lights.	High level replacements / maintenance	F&E	1.00	APPROVED May be better from a H&S perspective and more economical to do this all in one year	
Provision for maintenance works at closed cemeteries	3	50,000	50,000	50,000	50,000	Works required at closed cemeteries i.e Paths, Walls etc. In the last two years works has been needed not previously budgeted	Insurance risk	SDS	0.20	NOT SUPPORTED	
Cemeteries System	3	50,000				Critical to operate service and legal requirements for record keeping  Replacement of rotten external stud wall above	Old database not supported going forwards (365 / Windows 10) so need a new system. There are financing options available. Possible structural failure condensation identified	SDS	1.00	APPROVED	
Bedwell Community Centre roof fascia replacement	3	50,000				perimeter windows	as causing some problems only part of structure inspected so need to undertake detailed full survey in the new year to expose concealed structural timbers to confirm full scope of the works	F&E	Survey results first, hold £ in the reserve	DEFERRED	
Bedwell Neighbourhood centre canopy repairs	3	30,000	0	0	0	Metal gutters and structure corroded with risk of pieces falling onto the public below.  Cameras are at a high risk of failure, due to a lack of	Detailed survey to be carried out on structure to confirm full scope of the works	F&E	1.00	APPROVED	
Replacement Camera programme	3	25,000	35,000	40,000	10,000	investment in a replacement programme this is for the end of life replacement for 18 cameras in 22/3, and 24 cameras in 23/24, and 26 cameras 24/25, plus 7 cameras 25/26.		C&N	0.60	APPROVED	
MSCP resurface worn stairwell floor	3	20,000	40,000			Health and safety slip hazard	Phased over 2 years £20K increase in capital programme for 2022/23 to complete the 2 higher use staircases and the remaining 2 in 2023/24	F&E	1.00	APPROVED May be better from a H&S perspective and more economical to do this all in one year	
Bedwell CC - Replace extract fans and electric heaters	3	5,000				To ensure internal environment for occupation	Extract fans need repair or replacing to reduce condensation and ensure adequate ventilation. The heating system was repaired and replaced two years ago, the electric heaters are supplementary and can be repaired/replaced as required.	F&E	0.80	APPROVED	
ASB team mobile camera	3	5,000	5,000	5,000	5,000	This is a mobile camera replacement programme as required to ensure we can place cameras I hotspots of ASB as they occur	As required by the SoSafe Community Safety action and agreed by RAG members.	C&N	0.80	APPROVED	
BTC Essential works - Replace / upgrade doors, Lighting and control upgrade and replacement of lift in the new block	3		195,000			Replacing end of life lighting with LED complying with regulations (fluorescents phased out). Existing doors in poor condition requiring replacement and some fire upgrades. Lift end of life and risk of disruption and failure causing access difficulties to all areas and non compliance.	All works identified during the 2018 condition survey by specialist M&E consultant. Subject to repair responsibilities and check with lift insurers recommendations report.	F&E			
Chells manor - lightning upgrade Westin Road ABS Pump	3	0	10,000 5,500	0	a	To ensure compliant lighting levels rep[lacing with LED. Legislation in Sept 2023 phasing out the sale of Flourescent lights. To prevent site flooding	Fitting LED will improve energy efficiency and saving on electric costs.	F&E SDS			
Mandatory requirements total Priority 4: Schemes to maintain operational efficien	cy	760,000	415,500	170,000	65,000						
St Nicholas Pavilion reroofing	4	150,000				Whilst the mod has shown no signs of leaking the flat roof is in very poor condition therefore there is a risk of water ingress causing damage to the flabric and structure leading to possible health and safely issues (Electrics) and disruption to the operations and possible closure of areas or the whole building.	There are currently no bookings until May 2023, bookings are limited and there will not be a return on investments, whilst patchwork repairs may be wable this is dependent on the location of any leaks and if it is repairable the council needs to decide the future life of this facility. The asset team are looking to bease the facility, so it needs to be decided if the investment is viable on a financial lease return to Salva.	F&E	defer doing it and look at community centre review	DEFERRED	
Lift replacement at SALC	4	140,000	0	0	O	As identified in 2019, the lift will need replacing during 2023, and a temporary lift solution may be required whilst works are being undertaken		C&N	0.80	APPROVED	
Ridlins Athletics	4	100,000		0	0	Condition surveys have been completed for the building M&E plus athletics track and supporting facilities there will be a requirement for major capital spend within the next three years	The budget is to repair the floodlights and carry out essential H&S works and maintain operational integrity	C&N	0.80	APPROVED	
Replacement bridge at Golf Centre & other bridge works	4	90,000				A bridge collapsed this year due to erosion caused by flooding at the course, the bridge is in a key location and needs to be resolved to avoid injury to players, other bridges are at risk due to erosion and works will need to be undertaken to avoid further damage to bridges	Cost is a worse case estimate, we are hoping to reduce to 70k	C&N	0.60	APPROVED	
St Nicholas Pavilion replace windows	4	75,000				Windows end of life. Replacement to ensure security, ventilation and improved energy performance	The windows are made of soft wood and are rotting. If this was agreed the works would need to be completed in conjunction with the roof works as the windows are at high level. Given the dilapidations of this facility and the investment required the council needs to decide its future viability.	F&E	defer doing it and look at community centre review	DEFERRED	
Chells Manor - boiler replacement and hot water works	4	50,000				Risk of boller fallure - Building will not operate if boller falls. Has been regular serviced high risk of fallure end of life ,	The boiler is currently working and serviced on a regular basis, further investigations are taking place to understand if parts are available should it fail. The boiler has reached the end of its economic life. The facility has been well used as a vaccination centre but the general usage of the facility is very low	F&E	defer doing it and look at community centre review	DEFERRED	
Maxi Truck EL 4WD 48V 4WD articulated truck with a 1,000kg - 1,500kg load capacity	4	35,000	0	0	0	Had been budgeted for in 21/22 but the funding was reallocated to purchase a replacement mower which was required urgently		SDS	1.00	APPROVED	
Flat block waste management infrastructure	4	30,000				Pilot project to deliver improvements for access, infrastructure, receptacles and signage to support increased recycling in flat blocks, and to enable future food waste collections	Linked to national Resources & Waste Strategy, and requirement to provide separate weekly food waste service to all residents in future. The pilot will inform a future capital bid for wider roll-out	SDS	0.60	APPROVED	
Vehicle (Grounds)	4	30,000	_			Commercial skip development impacts on being able to service grounds after ceasing yellow huts	Only highlighting at this stage as potential to convert existing Housing vehicle if it can be	SDS	0.80	APPROVED	
	4	30,000	0				convert existing Housing vehicle if it can be transferred	SDS	0.80		
Vehicle (Play) St Nicholas play centre roof	4	30,000	0	0	o	Play Fitter - New duty on service review. Box Van Anot covering end of life. Reroofing required to ensure building operations are maintained. Risk of water ingress causing damage to the fabric and structure leading to disruption to the operations and possible closure of areas or the whole building.	The building is of a modular type which is in poor condition and beyond its designed lifespan it is supported by metal sturks which have twisted over time, whilst it is structurally sound the consequence is that the building is no longer true or square which has resulted in pools of water laying on the root as there is no not any falls to drainage, and the root surface is in poor condition. Whilst there is no sthere is no that gat this time there is a risk that the roof will fall although some patch repairs may be valide dependant on the source of the problem. What has not been costed is that the roof insulation would also likely inseed to it that the roof insulation would also likely inseed to	SDS F&E	0.80  defer doing it and look at community centre review	APPROVED  DEFERRED	
							be replaced				

## APPENDIX A - GENERAL FUND GROWTH BIDS

Stevenage

Scoring: not agreed 0

				2024/2025	2025/2026				Average Score	
Scheme	Priority	Growth Bid	Growth Bid	rowth Bid Growth Bid Gro		Reason for Request	Any other Relevant Information	Service	for 22/23	OUTCOME
		£	£	£	£				Growth Bid	
Priority 4: Schemes to maintain operational efficience	y (Cont.)									1
						Roof covering end of life and in very poor condition.  Reroofing required to ensure building operations are	This facility is well used by the Living Room Charity,			
						maintained. High Risk of water ingress causing damage	the modular building itself is in fair condition but			
8-10 The glebe roof replacement	4	30,000			,	to the fabric and structure leading to possible health and safety issues (Electrics) and disruption to the operations	the roof is in very poor condition and it is surprising that no leaks are apparent, patch repairs	F&E	1.00	APPROVED
8-10 The glede roof replacement	4	30,000	U	0		and possible closure of areas or the whole building.	may be able to rectify any problems that do occur but this is dependent on the type of problem and	FOLE	1.00	APPROVED
							its location.			
AFFER (Indianated as associated	4	30,000				Water ingress causing water damage to stall holders	Risk of compensation - loss of income	F&E	1.00	400000150
MSCP / Indoor Market guttering	4	30,000				possessions and leading to possible closure.		FOLE	1.00	APPROVED
						Roof covering end of life. Reroofing required to ensure building operations are maintained. Risk of water ingress	The main roofs of the Oval have all been replaced, with the exception of this part of the building			
						causing damage to the fabric and structure leading to possible health and safety issues (Electrics) and	which is hired to and used by Barnardo's used as a family central, patchwork repairs can be		defer doing it and look	
The Oval reroofing ('youth wing')	4	30,000				disruption to the operations and possible closure of	undertaken depending on the location and nature	F&E	at community centre	DEFERRED
						areas or the whole building. Used as preschool, the rest of the roofs at the Oval have been done, if it leaks it can	of the problem.		review	
						be patched repaired				
						Inflation increase on 2017 figures	Relevant for 2022/2023. The budget has not			
Play Area Improvements	4	25,515	0	0			increased in line with inflation so we will achieve less for the investment.	SDS	1.00	APPROVED
Rotary Gang Mowers	4	25,000	0	0		Meadow Grass - increased demand of meadow areas	Would have to outsource if do not buy	SDS	1.00	APPROVED
			25 000			under bio-diversity agenda Replacement for end of life equipment - critical to role	They are approx. £25k each. Ideally we would want			
Wood Chippers	4	25,000	25,000	0			one in 22/23 and one 23/24.	SDS	1.00	APPROVED
Water Tank and system, Shephalbury Bowls	4	15,000	0	0	0	Failed system which means manual watering / cost		SDS	0.40	NOT SUPPORTED
Replacement for Cemeteries Dump Truck	4	15,000	0	0	0	End of life vehicle  Heaters end of life and high risk of failing, Fix on fail	Use of Temporary heaters could be used if	SDS	1.00 cost estimate now	APPROVED
Douglas Drive day centre replace electric wall-	4	10,000				approach could be adopted.	heating fails	F&E	approx £2.5K so	REMOVED
heaters	•			1					removed from the capital bids	
Applied Sweeper LK18 HCF	4	5,800 5.800	0	0	0	top-up as existing budget too low	Current budget is for £58,200	SDS SDS	1.00	APPROVED APPROVED
Applied sweeper green machine LK18 HCE	4	5,800	°	0		top-up as existing budget too low Roof covering end of life. Reroofing required to ensure	Current budget is for £58,200	505	1.00	APPROVED
						building operations are maintained. Risk of water ingress causing damage to the fabric and structure leading to		1		
Bedwell Community Centre reroofing	4		125,000			possible health and safety issues (Electrics) and		F&E		
				1		disruption to the operations and possible closure of areas or the whole building.		İ		
							Worn pitched roof covering to the older part of the			
						Risk of water ingress causing damage to the fabric and structure. Risk of flood causing areas of centre to close.	building – this is a metal sheet system made to			
							look like traditional tiling –Survey Report recommends to renew the covering in 2021 2022 at			
							an estimated cost £50k there is no evidence of any			
Peartree pavilion - reroofing	4		100,000				current leaks. Very poor condition of Shower Area requiring total	F&E		
							upgrade/refurbishment - at estimated cost then of £30k there is limited use of the showers			
							ESON CHEE IS MINITED USE OF CHE SHOWERS			
						Roof covering end of life. Reroofing required to ensure building operations are maintained. Risk of water ingress	There is no evidence of leaks in the roof and gutter, can take a fail and fix approach			
						causing damage to the fabric and structure leading to	can take a rail and rix approach			
KGV reroofing and gutter replacement	4		75,000			possible health and safety issues (Electrics) and disruption to the operations and possible closure of		F&E		
						areas or the whole building.				
						Extend life of asset (10-15 years) If refurbishment not	This is occupied by the Community Centre			
						carried out now full reroofing required in next couple of years Metal corrosion treatment	preschool, the metal of is unique and failure to treat with anti-corrosion treatment within the next			
St Nicholas Annex refurbish metal roof	4		60,000			,	two years will result in the roof being beyond	F&E		
							repair and will therefore cost significantly more to replace			
						Roof covering end of life. Risk of water leaks	To keep the centres maintained and in good-			
Mobbsbury Way Neighbourhood Centre canopy-	4		30,000			dripping on the public using the shops and causing- long term deterioration of the structure. If left this-	condition to encourages use by the public.  Easier to retain and attract new lettings	F&E	no longer required so removed from the	REMOVED
reroofing	4		30,000			could lead to collapse.	Detailed survey to be carried out as part of the	F&E	removed from the capital bids	KEMOVED
							stock condition surveys			
Play Area Improvements	4	0	24,220	0		Inflation increase on 2017 figures	Relevant for 2023/24. The budget has not increased in line with inflation so we will achieve	SDS		
i siy Acu improvenients		·	24,220		,		less for the investment.	353		
KGV Pavilion Replace electric heating and lighting	4		20,000			maintaining the operation of the building, working at the	The system is adequate for this building at the moment and a fail and fix approach should be	F&E		
						The selection of the se	adopted.			
BTC - Replace roof lights, gutters and fascia's to the old blo	4			150,000		The rainwater goods, roof lights and fascia's are at the en	survey by specialist M&E consultant. Subject to	F&E		
Through add an arrange and a						Roof covering end of life. Reroofing required to ensure bu	repair responsibilities Building leased and is currently part of the			
Timebridge - reroofing	4			85,000			community asset review	F&E		
						Roof covering end of life. Risk of water leaks dripping on the public using the shops and causing long term	To keep the centres maintained and in good condition to encourages use by the public. Easier	1		
The Glebe Neighbourhood Centre canopy reroofing	4			40,000		deterioration of the structure. If left this could lead to	to retain and attract new lettings Detailed survey to be carried out as part of the	F&E		
						collapse.	stock condition surveys	1		
				1		Roof covering end of life. Reroofing required to ensure building operations are maintained. Risk of water ingress	Included in the locality review	İ		
St Nicholas CC reroofing	4			1	125,000	causing damage to the fabric and structure leading to possible health and safety issues (Electrics) and		F&E		
Ĭ						disruption to the operations and possible closure of		1		
				1		areas or the whole building.		İ		
The Oval - replace heaters in Hall and dining room	4				10,000	Risk of heaters failing - operations of building affected.	Life of building unknown	F&E		
Maintain operational efficiency total		967,115	429,220	275,000	135,000			1		
Priority 8: Schemes that further the Council's Corpora Shrub bed programme	ate Plans 8	133,000	133,000	133,000	133,000	Replacement / improvements to public realm		SDS	0.60	APPROVED
Core ICT Equipment for Additional Staff	8	70,000	0	0		Roll-out of new ways of working	Only £30K for HRA share was approved for 22/23,	IT	1.00	APPROVED
				1		Current plan (2017-2022) for review in 2022.	not the General Fund as well. Intend to incorporate Biodiversity Net Gain			
Review of Biodiversity Action Plan	8	12,000	0	0	0	1	proposals which will generate income (from developers) to support delivery of BAP.	SDS	0.60	APPROVED
				1		As per Oct Exec. Report. Grants to help local Stevenage	accompany to support utilivery of par-	1		
SBC grants to businesses to reduce their carbon emissions	8	8,000	8,000	8,000	8,000	businesses decrease this carbon emissions.		P&R	0.40	NOT SUPPORTED
Cashless on street parking transition	8	0	60,000	60,000	0	Replace the current cash only on street parking machines		P&R		
Council's Corporate Plans total		223,000	201,000	201,000	141,000	with, cashless / and card only machines.		1		
Priority 11: New Burdens						Possible 23/24 - new burden funding	Based on food only. If went for recycling option	1		
	11	0	630,000	0	0		would be £700,000 but funding may be available	SDS		
Recepticles for new rounds etc						Possible 23/24 - new burden funding	for some of this Need to use other resources to fund this until the	1		
Food collection vehicles (x5)	11	0	160,000	0	0	.,	new burden funding is received. Increased to reflect food only based on further work done on	SDS		
				Ī		ı		1	1	
							Round-Op	Į.		
New Burdens total		0	790,000	0			Round-Op			

APPENDIX A - GENERAL FUND GROWTH BIDS

Scoring:	
not agreed	0
agreed	1

							Stevenage BOROUGH COUNCIL		not agreed agreed	0 1
Scheme	Priority	2022/2023 Growth Bid	2023/2024 Growth Bid	2024/2025 Growth Bid	2025/2026 Growth Bid	Reason for Request	Any other Relevant Information	Service	Average Score for 22/23 Growth Bid	ОИТСОМЕ
		Return on invest								
		Income generati								
		Mandatory requ			)					
		Schemes to main		efficiency						
		Match funding s								
		Financial efficier								
	Priority 7	Urgent works (th								
		Schemes that fu Schemes that re								
		Schemes that re				Register				
		New Burdens	velop or improve	partnership worki	ng					
		recw builders					1			
Growth bid priority			2022/2023	2023/2024	2024/2025	2025/2026	TOTAL	Ì		
Priority 1	Return on inv	estments	0	0	0	0	0			
Priority 2	Income gener	rating	0	0	0	0	0			
Priority 3	Mandatory re	quirements (inclu	760,000	415,500	170,000	65,000	1,410,500			
Priority 4		naintain operation	967,115	429,220	275,000	135,000	1,806,335			
Priority 5	Match fundin		0	0	0	0	0			
Priority 6	Financial effic		0	0	0	0	0			
Priority 7		(that reduce the r		0	0	0	0			
Priority 8		further the Counc		201,000	201,000	141,000	766,000			